

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Spring 2010 Levee Inspection Results**

Sutter Maintenance Yard Maintenance Area 0017

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Sutter Maintenance Yard Maintenance Area 0017

Waterway			Bank	Unit Miles
Unit No. 01 Lake County Sutter Maintenance Yard - Middle Creek			Left	3.90
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/18/2010 - 5/18/2010			
DWR Inspector	Bob Duffey			
Accompanied By	Bryan Reniff Sutter Yard			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard Maintenance Area 0017

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lake County Sutter Maintenance Yard - Middle Creek						Left	3.90	05/18/2010 05/18/2010	Bob Duffey

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	4.18	7.30	Earthen Levee	Trim / Thin Trees	WS	U	Thin trees to allow visibility of the ground and room to flood fight.	39.142155 ° -122.902343 °	39.118735 ° -122.884892 °	2 Y
2	4.18	7.31	Earthen Levee	Vegetation	WS	U	Remove the wild growth other than native grasses from the levee slopes.	39.142155 ° -122.902343 °	39.118675 ° -122.884772 °	1 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard Maintenance Area 0017

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lake County Sutter Maintenance Yard - Middle Creek	Left	3.90	05/18/2010 05/18/2010	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	4.18
End Levee Mile	7.30
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

View of the vegetation on both sides of the levee & water on the toe of the levee in one location.

rduffey_s_20100609_038.jpg



Levee Mile Report Line	1
Start Levee Mile	4.18
End Levee Mile	7.30
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

View of the trees on the waterside slope of the Levee.

rduffey_s_20100622_064.jpg



Levee Mile Report Line	2
Start Levee Mile	4.18
End Levee Mile	7.31
Location	Water Side
Category	Earthen Levee
Item	Vegetation

view of the six-foot crown levee & heavy vegetation on waterside slope.

rduffey_s_20100609_039.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard Maintenance Area 0017

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lake County Sutter Maintenance Yard - Middle Creek	Left	3.90	05/18/2010 05/18/2010	Bob Duffey

Levee Mile Report Line	2
Start Levee Mile	4.18
End Levee Mile	7.31
Location	Water Side
Category	Earthen Levee
Item	Vegetation

View of the vegetation on the both slopes of the levee.

rduffey_s_20100622_063.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected